

DEPARTMENT OF HOMELAND SECURITY
U.S. COAST GUARD
INTERMODAL CONTAINER INSPECTION REPORT

1. MISLE Activity Number:

2. Inspection Type:

Response

3. Container Number: <u>00LV4347696</u>	4. Country of Origin:
5. Container Type: <u>Freight</u> / Tank / Reefer	6. Date of Inspection: <u>21 NOV 24</u>
7. Inspection Location: <u>LBCF</u>	8. Time of Inspection: <u>1357</u>
9. Involved Party: U.S. DOT HAZMAT Registration Number: Address:	10. COTP Zone: <u>SECTOR LALB</u>
	11. Seal Removed Number:
	12. Replacement Seal Number:
	13. ACEP Number:
	14. CSC ID Number:
15. Shipment Prepared By: 49 CFR <u>IMDG Code</u>	
16. Inspection conducted as part of Multi-Agency Strike Force Operation? Yes <input type="radio"/> No <input checked="" type="radio"/>	

No.	Description	Cite (Convention)	Action Taken or Required
01	Containers were knocked off the vessel into the water, sustaining structural damage	49CFR 453.1	Detained

Additional Instructions: Supply Shipping Papers Contact USCG @ 310-521-3745
Sector LALBfac@USCG.mil

18. Control Action Taken:

Container Detained Repair Required HAZMAT UN ID #(s) _____

Shipment Detained Re-Inspection Required HAZMAT Class(es) _____

19. Authorities cited to support actions: 49 CFR 453.1 / 33 CFR 160.109 / 33 CFR 6.04-7

Copy provided to: _____ (Owner/Shipper/Agent/Custodian - Printed Name) _____ (Signature)

USCG Container Inspector: MST3 Justin Holtz Justin Holtz
(Duly authorized Container Inspector - Printed Name) (Signature)

This deficiency report constitutes written notice of discrepancies discovered, order for detention, and/or corrective action required. Separate notice will be given if penalty action is initiated.